



Table 3 - Barrier & Approach Protection Recommendations (2020)
Township of Georgian Bluffs

February 2021

201-05626-00

Structure No.	Upgrade*	Timing (Years)
D-0001	<ul style="list-style-type: none"> Replace Damaged Barrier 	1-5
D-0003	<ul style="list-style-type: none"> Install Barrier and Approach Protection 	1-5
D-0004	<ul style="list-style-type: none"> Install Barrier and Approach Protection 	1-5
D-0005	<ul style="list-style-type: none"> Install Barrier and Approach Protection 	1-5
D-0006	<ul style="list-style-type: none"> Install Barrier and Approach Protection 	1-5
D-0008	<ul style="list-style-type: none"> Install Barrier and Approach Protection 	1-5
D-0009	<ul style="list-style-type: none"> Install Barrier and Approach Protection 	1-5
D-0010	<ul style="list-style-type: none"> Install Barrier and Approach Protection 	1-5
D-0011	<ul style="list-style-type: none"> Install Barrier and Approach Protection 	1-5
D-0012	<ul style="list-style-type: none"> Install Barrier and Approach Protection 	1-5
D-0013	<ul style="list-style-type: none"> Install Barrier and Approach Protection 	1-5
D-0014	<ul style="list-style-type: none"> Install Barrier and Approach Protection 	1-5
K-0001	<ul style="list-style-type: none"> Install Barrier Protection 	1-5
K-0003	<ul style="list-style-type: none"> Install Barrier and Approach Protection 	1-5
K-0004	<ul style="list-style-type: none"> Install Approach Protection 	1-5
K-0011	<ul style="list-style-type: none"> Install Barrier and Approach Protection 	1-5
K-0012	<ul style="list-style-type: none"> Install Barrier and Approach Protection 	<1
K-0014	<ul style="list-style-type: none"> Install Barrier and Approach Protection 	1-5
K-0017	<ul style="list-style-type: none"> Install Barrier and Approach Protection 	1-5
S-0004	<ul style="list-style-type: none"> Install Barrier and Approach Protection 	1-5

*Recommendation: That an urgent interim measure to reduce speed limit at all the above noted structures to 40 km/hr. be implemented until the upgrade structure barrier and approach protection improvements are completed.